

Kniveton playground inspection

Action log

13 September 2022

Playing field

Ref	Recommendation	Work requested	Contractor	Update
1	Level surface on playing field gate entrance	3/22	Fox Landscaping Quote March 2022	JPFC/0322/05 Resolved: to obtain 2 more quotes for consideration. 3 suppliers contacted. 1 agreed to visit site 10/5/22 but didn't
2	Make good uneven surface – toddler swing	3/22	Fox Landscaping Quote March 2022	
3	Secure down the lifting matting under swing seats and around supports which is s lifting under seats - 2 swing equipment	3/22	Fox Landscaping Quote March 2022	
4	Secure down grass matting lifting at the edges – toddler swing.	3/22	Fox Landscaping Quote March 2022	
5	Clean off algae present on barriers and decking – multiplay unit.	3/22	Fox Landscaping Quote March 2022 Fox Landscaping Quote March 2022	
6	Secure Down various parts of the surfacing which are rising causing a potential trip hazard – multiplay unit.	3/22 & 8/22	Fox Landscaping Quote March 2022	Asked for separate quote 24/8/22 FC/0722/06b
7	Remove moss, weeds, and algae – path around muga.	3/22	Fox Landscaping Quote March 2022	

8	Gate - adjust gate / posts / fit new rubber buffer to ensure a spacing of at least 12 mm Throughout the range of the gate to remove the entrapment. The 12 mm gap also Should apply on the hinge side of the gate	19/3/22	Cllr Savidge has fixed Cllr Savidge to do this over Easter or Summer 2022	
9	Fences - a number of fence posts have decay below ground level, making some wobble. Monitor and replace when necessary.			
10	Litter bin – move so 2-3 metres away from gate			
11	Clean the bin			
12	Benches - some rot at and below ground level. Monitor and replace when necessary			
13	Goal posts - de-scale back to good base material and coat with lead free paint, using Appropriate precautions.	11/4/22	Stuart Ford done this July 2022	
14	Basket ball - de-scale back to good base material and coat with lead free paint, using Appropriate precautions			
15	Railing wire x 1 is damaged in goal panel nearest field goals. Repair.			

March 2022 quote – Fox Landscaping

- Level Surface on playing field gate.
- Make good, uneven surface – toddler swing
- Secure down the lifting matting under swing seats and around the supports, which is lifting under seats – 2 swing equipment.
- Secure down grass matting, lifting at the edges – toddler swing
- Secure down various parts of the surfacing, which are rising causing potential trip hazard – multi play unit.
- To all the above we shall add topsoil and grass seed where needed
- Remove moss and algae – path around the muga, apply wet and forget.
- Remove any waste
- Any extra work requested and carried out that is not listed above will be invoiced accordingly.

The cost for the above works totals **£790.00+VAT**.

Stuart Ford Work July/Aug 2022

Prepare and paint School Playground Goalposts.

Affix aluminium sheet covers to 2 x bins

Affix 5 x bolts and 6 x nuts to games court frame